

User's Instructions for Gateway Model No. 80108



FITTING INSTRUCTIONS

1. Hold mask in one hand over mouth and nose with straps around back of head. Pull lower strap over head and fit around neck. Pull upper strap over head and place it above ears.
2. Adjust tension in straps by positioning straps on head until you obtain a positive face seal.
3. Perform a User Seal Check prior to each wearing. It is the wearer's responsibility to obtain a proper fit. Each time respirator is used, wearer must test fit by cupping both hands over the respirator and exhaling vigorously. If air is felt flowing around nose or leaking around edges of the respirator, reposition or tighten straps until air is no longer escaping when wearer exhales. If you CANNOT achieve a proper face seal, DO NOT enter the contaminated area. See your supervisor.

WARNING

- A. Before occupational use of this respirator, a written respiratory protection program meeting all the local government requirements must be implemented. In the United States employers must comply with OSHA 29 CFR 1910.134 which includes medical evaluation, training, and fit testing.
- B. This respirator does not supply oxygen. Use only in well ventilated areas containing sufficient oxygen, at least 19.5%, to support life.
- C. Do not use when concentrations of contaminants are unknown; at levels dangerous to health and life, in excess of 10 times the permissible exposure limit (PEL) or in excess of other regulations.
- D. Leave contaminated area immediately if respirator is damaged, or if any physical distress such as breathing difficulty, dizziness or nausea occurs.
- E. Do not alter, modify or misuse respirator.
- F. Facial hair, beards or certain facial characteristics may prevent a proper fit and thus prevent the use of this respirator.
- G. Keep unused respirators in the display box, stored in a cool, dry, uncontaminated area, away from direct sunlight until use.
- H. Dispose of respirator after single use, increased breathing resistance or hygiene damage.

USE RESTRICTIONS

DO NOT USE in spray painting or sandblasting operations.

DO NOT USE for protection in asbestos environments.

DO NOT USE for protection against vapors or gases.

DO NOT USE for welding applications or near any welding activities.

DO NOT USE against any contaminant whose concentration is unknown, or immediately dangerous to life.

DO NOT USE against concentrations of Dust and Mists which exceed the maximum use concentration or 10 times contaminant's permissible exposure limit established by OSHA.

USE AGAINST non-oil particulate aerosols, such as coal, iron ore, cotton, flour, and for sprays that do not emit vapors or gases.

S - Special or Critical User Instructions - This Gateway Safety filtering face piece respirator Model #80108 is marketed and sold by Gateway Safety, Inc. under a production agreement with approval holder San Huei United Co., Ltd. in accordance with NIOSH TC-84A-7631.